

# INSPECTION NOTICE (Results/Remedies)



1	Date:	11/22/2020	_						
2			ABI 4 A 4						
		RENCE TO THE BUY-		_		11/10/2			
	between	Julene Kra Lorenzo G. Fuer	use	And	Harry Krause		(hereafter		
					Tanya M. Fuer		(hereafter	tne	"Buyer")
7		ıl property commonly k Kalispell	diown as 17	1 Ploneer Ko	ad .		MT		0001
8		Marropera	<del></del>				MI	<del></del>	9901
-	BUYER H	EREBY GIVES NOTIC	CE TO SELLER	R OF DISAPPRO	OVAL OF THE FOLL	OWING ITE	MS <sup>.</sup>		
		he relevant portion of					*1.4.		
11	Electric			.,	<b>,</b>				
12	Open win	cing from service t	oanel near er	atrance of dri	veway going unde	raround sub	iect to n	hvei	cal
13	Open wiring from service panel near entrance of driveway going underground subject to physical damage and possible shock.								
	Garage has no GFCI and is missing electrical outlet cover plates in various locations. The outlet on the South Wall nearest to east corner of garage is not functioning at this time.								
15	The outlet on the south wall hearest to east corner of garage is not functioning at this time.  No main disconnect breaker in garage sub panel.								
16				-					
	Caulking Crack in	J: n the wall seam of	the Southwee	st bedroom.crs	icked seems on w	.17 in lively	a room		
18 19	Caulking	around windows,	loors, corner	es, utility pe	netrations.	iii in iivii	ig room.		
20	Wisible				·				
21	entry.	moisture/water pre	sent, active	e leak on Nort	n wall in crawi	space acros	ss from cr	awı	space
22	_								
23	No seisi	alc restraint on a	hot water he	eater.					
24	Water to	est results have no	ot returned.						
25									
26									
27									
28									
29									
30 31									
32									
33									
34									
35									
36									
37									
38									
39									
40 41									
42									
43									
44									
45									
46									
47				•					
48									
49									
50 51									
51 52	Γ -	ן רו							
JZ	LGF	] , [sms	@ 281 <u>9</u>	Montana Associa	tion of REALTORS®		,		
	B	uyer's Initials	@ ZU10	Inspection Notice		<del></del>	Seller's I.	nitials	<del></del>
	_	• • • • • • • • • • • • • • • • • • • •		Page 1			++1.*· * 1		

55	Buyer elects to nego	otiate the items of disapprov	val described above and offers the	following resolution:
56	Seller to have a qualifi		e and repair the electrical i	: "
57 58		litional items.		
59	Buyer's inspection perio		-1	
60	Buyer's inspection perio	d to be extended for bi	mry the water test.	
61				
62				
63				
64				
65				
66				
67				
68				
69				
70				
71				
72 73				
74				
75				
76				
77				
78				
	If Seller and Buver agree to t	the remedies specified abo	ve, this document shall constitute	an amendment to the Buy
	Sell Agreement referred		hall be an integral part	of this transaction.
81			to the condition(s) and proble	
82	5:00 p.m. (Mountain Time) on	12/11/2020	(Date).	(:,
83	Authentision	11/22/2020	— Authentiskser	11/22/2020
84	Lovenzo G. Fuentes	/	Tanya M. Fuentes	/
85	(Buyer's Signature)	Date	(Buyer's Signature)	Date
86				
	Seller agrees to the terms and	conditions as stated herein	above.	
88				
89		/		
	(Seller's Signature)			/
	• •	Date	(Seller's Signature)	/
91	Krause	Date	(Seller's Signature)	/ Date
91 92	Krause		, ,	/ Date
91 92 93	Krause	Notice (Seller's Response)		Date
91 92 93 94	Krause	Notice (Seller's Response)	, ,	Date
91 92 93 94 95	Krause  ☐ Modified per Inspection	Notice (Seller's Response) ِ Ş		// Date
91 92 93 94 95 96	☐ Modified per Inspection ☐ Rejected by Seller	Notice (Seller's Response)		/ Date 
91 92 93 94 95 96 97	☐ Modified per Inspection ☐ Rejected by Seller	Notice (Seller's Response) ِ Ş		/ Date 
91 92 93 94 95 96 97 98	Modified per Inspection  ☐ Rejected by Seller  Selle	Notice (Selfer's Response) / / er's Initials Date	/ / Seller's Initials Date	_
91 92 93 94 95 96 97 98	Modified per Inspection  ☐ Rejected by Seller  Selle ☐ Buyer elects to termina	Notice (Selfer's Response)  / / er's Initials Date ate the Buy-Sell Agreement		_
91 92 93 94 95 96 97 98 99 100	Modified per Inspection  ☐ Rejected by Seller  Selle	Notice (Selfer's Response)  / / er's Initials Date ate the Buy-Sell Agreement	/ / Seller's Initials Date	_
91 92 93 94 95 96 97 98 99 100 101	Modified per Inspection  ☐ Rejected by Seller  Selle ☐ Buyer elects to termina	Notice (Selfer's Response)  / / er's Initials Date ate the Buy-Sell Agreement	/ / Seller's Initials Date	_
91 92 93 94 95 96 97 98 99 100 101 102	Modified per Inspection  ☐ Rejected by Seller  Selle ☐ Buyer elects to termina Buyer and the Buy-Sell Agree	Notice (Seller's Response)  / / er's Initials Date ate the Buy-Sell Agreement sement is terminated.	/ / Geller's Initials Date  referred to above. All earnest mor	ney shall be returned to the
91 92 93 94 95 96 97 98 99 100 101 102	Modified per Inspection  ☐ Rejected by Seller  Selle ☐ Buyer elects to termina	Notice (Selfer's Response)  / / er's Initials Date ate the Buy-Sell Agreement	/ / Seller's Initials Date	_

NOTE: Unless otherwise expressly stated the term "Days" means calendar days and not business days. Business days are defined as all days as except Sundays and holidays. Any performance which is required to be completed on a Saturday, Sunday or holiday can be performed on the next business day.

© 2018 Montana Association of REALTORS® Inspection Notice, March 2018 Page 2 of 2

Exterior				
Fascia cont:				
Material	☐ Wood X Fiberboard ☐ Aluminum/Steel ☐ Vinyl ☐ Stucco ☐ Recommend repair/painting ☐ Damaged wood Other:			
Condition	Marginal Poor			
Comments				
Flashing				
	□ None			
Material	☐ Wood ☐ Fiberboard ☒ Aluminum/Steet ☐ Vinyl ☐ Stucco ☐ Recommend repair/painting ☐ Damaged wood Other:			
Condition	Marginal Poor			
Comments				
Caulking				
	None			
Condition	Satisfactory Marginal Poor Recommend around windows/doors/masonry ledges/corners/utility penetrations			
Comments	Recommend caulking around windows, doors, corners, utility penetrations.			
Windows/Scr				
Condition	☐ Marginal ☐ Poor ☐ Wood rot ☐ Recommend repair/painting ☐ Recommend repair/replace damaged screens ☐ Failed/fogged insulated glass			
Material	☐ Wood ☐ Metal X Vinyl ☐ Aluminum/Vinyl clad			
Screens	☐ Torn ☐ Bent ☐ Not installed ☐ Seister of			
Comments				
Storms Wind				
	X None ☐ Not installed			
Condition	Satisfactory Broken/cracked Wood rot Recommend repair/painting			
Material	□ Wood □ Clad comb. □ Wood/Metal comb. □ Metal			
Putty	☐ Satisfactory ☐ Needed ☐ N/A			
Comments	do/Soundation			
	de/Foundation  Wall ☐ Concrete block ☒ Poured concrete ☐ Post-Tensioned concrete ☐ Not Visible Other:			
B.	Marginal Monitor Have Evaluated Not Evaluated			
Condition				
1	Concrete Slab N/A Not Visible Satisfactory Marginal Monitor Have Evaluated			
Comments Service Entr				
Location	▼ Underground  Overhead			
Condition	☐ Marginal ☐ Poor ☐ Weather head/mast needs repair ☐ Overhead wires too low			
Exterior rece	eptacles X Yes No Operable: X Yes No Condition: Marginal Poor			
GFCI presen	t X Yes ☐ No Operable: X Yes ☐ No ☐ Safety Hazard ☐ Reverse polarity ☐ Open ground(s) ☐ Recommend GFCI Receptacles			
1				


# **Exterior**

#### Service Entry cont.


Comments

Open wiring from service panel going underground subject to physical damage and possible shock. Recommend qualified electrician evaluate and repair. This is a potential safety hazard.

**Photos** 







terior Wall Construction
X Not Visible  Framed  Masonry Other:
X Not Visible ☐ Satisfactory ☐ Marginal ☐ Poor
N/A Weatherstripping: Marginal ☐ Poor ☐ Missing ☐ Replace Door condition:
■ N/A Weatherstripping: ■ Marginal ■ Poor ■ Missing ■ Replace Door condition: ■ Marginal ■ Poor
☐ N/A Weatherstripping: ☐ Marginal ☐ Poor ☐ Missing ☐ Replace Door condition: ☐ Marginal ☐ Poor
N/A Weatherstripping: ☐ Satisfactory ☐ Marginal ☐ Poor ☐ Missing ☐ Replace Door condition: ☐ Satisfactory ☐ Marginal ☐ Poor
Main entry and patio door are the same door.
leat pump #1
X N/A Location: Brand: Model #: Serial #:
Approximate Age:
Approximate Age: ☐ Satisfactory ☐ Marginal ☐ Poor ☐ Cabinet/housing rusted
<u></u>
Satisfactory Marginal Poor Cabinet/housing rusted
Satisfactory Marginal Poor Cabinet/housing rusted Electric Gas Other:
Satisfactory Marginal Poor Cabinet/housing rusted Electric Gas Other: Air cooled Water cooled Geothermal Heat pump  nect Yes No Maximum fuse/breaker rating (amps): Fuses/Breakers installed (amps):

#### **Garage/Carport** Trim cont. Condition Marginal Poor Recommend repair/replace Recommend painting Comments Floor X Concrete ☐ Gravel ☐ Asphalt ☐ Dirt Other: Material Condition X Typical cracks Large settling cracks Recommend evaluation/repair ☐ Safety hazard Source of Ignition within 18" of the floor X N/A Yes X No Comments Sill Plates ☐ None X Not Visible Туре Floor level Elevated Condition ☐ Rotted/Damaged ☐ Recommend repair Comments Overhead Door(s) □ N/A Material ☐ Wood X Fiberglass ☐ Masonite X Metal ☐ Recommend repair Condition Marginal Poor Hardware loose Safety Cable Recommended Recommend Priming/Painting Inside & Edges Yes X No Comments Exterior Service Door ☐ None Condition Comments Electrical Receptacles X Yes No Not Visible Operable: X Yes X No Reverse polarity Yes X No Open ground Yes X No Safety Hazard GFCI Present Yes X No Operable: Yes X No Handyman/extension cord wiring X Recommend GFCI Receptacles Recommend GFCI outlet in the garage. Comments The outlet on the South Wall nearest to east corner is not functioning at this time. Recommend qualified electrician evaluate and repair. **Photos**

	Living Room			
Living Room				
Location	First floor North			
Walls & Ceilin	Walls & Ceiling Marginal Poor Typical cracks Damage			
Moisture stair	ns ☐ Yes X No Where:			
Floor	Marginal ☐ Poor ☐ Squeaks ☐ Slopes ☐ Tripping hazard			
Celling fan	X None ☐ Satisfactory ☐ Marginal ☐ Poor ☐ Recommend repair/replace			
Electrical	Switches: XYes No XOperable Receptacles: XYes No XOperable Open ground/Reverse polarity: Yes XNo Safety hazard Cover plates missing			
Heating sourc	e present X Yes No Holes: Doors Walls Ceilings			
Doors	None Marginal ☐ Poor ☐ Cracked glass ☐ Broken/Missing hardware			
Windows	None None Marginal Poor Cracked glass Evidence of leaking insulated glass Broken/Missing hardware			
Comments	Cracked seems on wall in living room, recommend repair.			
Photos				

	Room (3)			
Room				
Location	First floor SW			
Type BEDROOM				
Walls & Ceiling Marginal Poor Typical cracks Damage				
Molsture stains ☐ Yes ☒ No Where:				
Floor	☐ Marginal ☐ Poor ☐ Squeaks ☐ Slopes ☐ Tripping hazard			
Ceiling fan	☑ None ☐ Satisfactory ☐ Marginal ☐ Poor ☐ Recommend repair/replace			
Electrical	Switches: X Yes No X Operable Receptacles: X Yes No Operable Open ground/Reverse polarity: Yes No Safety hazard Cover plates missing			
	ce present X Yes ☐ No Holes: ☐ Doors ☐ Walls ☐ Ceilings			
	ress restricted N/A Yes No			
Doors	□ None □ Marginal □ Poor □ Cracked glass □ Broken/Missing hardware			
Windows	☐ None ☐ Marginal ☐ Poor ☐ Cracked glass ☐ Evidence of leaking insulated glass ☐ Broken/Missing hardware			
Comments	Slight crack in the wall seam of the Southwest bedroom recommend caulking and repainting.			
Photos				

	Crawl Space
Crawl space	
	□ N/A
Туре	▼ Full crawlspace
Conditioned (	heated/cooled) Tyes XNo
Comments	
Photos	
Access	
Location	
1	m Access panel X In the crawl space
Comments	
Foundation w	
Condition	Marginal Have Evaluated Monitor Cracks Movement
Material	Concrete block X Poured concrete Stone ICF Wood Brick
Comments	Typical cracks. Visible moisture/water present, active leak, Recommend repair.
Photos	
Floor Material Condition Comments	☐ Concrete ☐ Gravel ☒ Dirt Other: ☐ Typical cracks ☐ Not Visible ☒ Vapor barrier present

### **Plumbing** Well pump cont. Pressure gauge operable Yes No Well pressure: Unknown, gauge was not accessible. X Not Visible Comments Sanitary/Grinder pump X N/A Operable: Yes No Sealed Crock Sealed crock: Yes No Check Valve Check valve: ☐ Yes ☐ No Shut-off Valve Shut-off valve: ☐ Yes ☐ No Vented ☐Yes ☐No Comments Water heater #1 □ N/A General Brand Name: Rheem Serial #: Unknown Capacity: 40 Approx. age: 20-25+ Type X Gas ☐ Electric ☐ Oil ☐ LP Other: Combustion air venting present X Yes ☐ No ☐ N/A Seismic restraints needed X Yes No N/A X Yes ☐ No Extension proper: X Yes ☐ No ☐ Missing ☐ Recommend repair Relief valve Improper material Vent pipe N/A ☐ Recommend repair N/A ☐ Recommend repair Condition Marginal ☐ Poor Comments Recommend seismic restraint on a hot water heater. Photos Water heater #2 X N/A General Brand Name: Serial #: Capacity: Approx. age:

## **Electric/Cooling System** Main panel Location Near front entrance Condition Poor Adequate Clearance to Panel X Yes No Amperage/Voltage ☐ Unknown ☐ 60a ☐ 100a ☐ 150a 🔀 200a ☐ 400a ☐ 120v/240v Breakers/Fuses X Breakers Fuses Appears grounded X Yes No Not Visible GFCI breaker ☐ Yes ☒ No Operable: ☐ Yes ☐ No AFCI breaker ☐ Yes 🕱 No Operable: ☐ Yes ☐ No ☐ Not Tested ☐ Copper X Aluminum ☐ Not Visible ☐ Double tapping of the main wire Condition: Main wire ☐ Marginal ☐ Poor Branch wire Branch wire condition Property Poor Recommend electrician evaluate/repair Romex BX cable ☐ Conduit ☐ Knob/Tube ☐ Double tapping ☐ Wires undersized/oversized breaker/fuse ☐ Panel not accessible ☐ Not evaluated Reason: Comments Panel size appeared to be compatible to service size. Sign of some overheating in panel. Appears to have been fixed. **Photos** Sub panel(s) ■ None apparent Location(s) Location 1: Garage Branch wire Copper Aluminum Safety hazard Neutral/ground separated: XYes No Neutral isolated: X Yes □ No Condition 図 Marginal Poor Comments **Photos**